

Internal
M0150041

From: Wayne Western
To: Berry, Emily; Paul Baker
Date: 12/8/2008 3:52 PM
Subject: Re: M/015/0041 DKG Quarry Bond Release
Attachments: Deny -suretyrelease-12082008.doc

Paul and Emily,

The request for bond release was inadequate because the Permittee did not include the proper bond release form.

I spoke to the Permittee and emailed the proper form.

Attached if a follow up letter.

Wayne

>>> Emily Berry 12/8/2008 2:49 PM >>>

0000

December 8, 2008

Karen Palmer
Diamond K Gypsum
1720 South Red Hills Drive
Richfield, Utah 84701-7003

Re: Additional Forms Needed for Bond Release, Diamond K Gypsum, DKG Quarry, M0150041,
Emery County, Utah

Dear Mrs. Palmer:

On December 8, 2008, the Division received your request for partial bond release for the DKG Quarry located in, Emery County, Utah. The Division cannot process the bond release application because the bond release form was not included.

In a telephone conversation, between you and Wayne Western on December 8, 2008, he explained what form was needed and emailed a copy of the form to you. Please return the application with the form. If you have any questions, you can call me at (801) 538-5261 or Wayne Western at (801) 538-5263.

Sincerely,

Paul Baker
Mining Program Coordinator
Minerals Regulatory Program

PPB:?:pb
Enclosure - Billing statement
cc: , BLM, FO (UTU-)
E-deny-close-date